

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/05/2018 10/05/2018	David Julian

LM Start		Rating **	M	Issue No.	14
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_14				
Comment Code					
Inspector Comment					
This district has a knowledge of how to conduct a flood fight but has not taken the class recently.					

No Photos

LM Start		Rating **	A	Issue No.	15
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_15				
Comment Code					
Inspector Comment					
District maintains supply of sand bags and gets other supplies from other districts.					

No Photos

LM Start		Rating **	A	Issue No.	16
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0755_01_f_2014_16				
Comment Code					
Inspector Comment					
MBK Engineering mailed a copy of the O/M Manul to the RD President in spring of 2017.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/05/2018 10/05/2018	David Julian

LM Start	0.00	Rating **	M	Issue No.	11
LM End	0.17	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.347123°	38.346773°
				-121.537572°	-121.538687°
DWR ID	DWR_RD0755_01_s_2017_11				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					
Crown vegetation should be mowed to allow inspection.					

Photo 1 of 1 : FA_2018_RD0755_177_11_20180925_00001.jpg



Crown vegetation should be reduced.

LM Start	0.17	Rating **	M	Issue No.	20
LM End	1.05	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.346757 °	38.343581 °
				-121.538675 °	-121.554301 °
DWR ID	DWR_RD0755_01_f_2016_20				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
The vegetation should be removed/managed to allow inspection of landside slope and toe.					

Photo 1 of 2 : FA_2018_RD0755_177_20_20181009_00040.jpg



View looking downstream at vegetation on the land side slope (October 2018).

LM Start	0.17	Rating **	M	Issue No.	20 (cont)
LM End	1.05	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA_2018_RD0755_177_20_20180925_00007.jpg



RD 755 looking downstream from levee mile 0.17-0.59.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/05/2018 10/05/2018	David Julian

LM Start	0.17	Rating **	M	Issue No.	19
LM End	1.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.346757 °	38.336409 °
				-121.538675 °	-121.564813 °
DWR ID	DWR_RD0755_01_f_2016_19				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
The tall weeds on the waterside slope and should be removed/managed to allow inspection. Large cactus (Century Plants) at LM 1.07 should be removed.					

Photo 1 of 2 : FA_2018_RD0755_177_19_20181009_00039.jpg



View looking upstream at vegetation on the water side slope (October 2018)

LM Start	0.17	Rating **	M	Issue No.	19 (cont)
LM End	1.84	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2018_RD0755_177_19_20180925_00006.jpg



RD 755 Levee mile 0.17-1.12 waterside looking downstream.

LM Start	0.24	Rating **	M	Issue No.	21
LM End	0.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.346275 °	38.346275 °
				-121.539838 °	-121.539838 °
DWR ID	DWR_RD0755_01_f_2016_21				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Trim trees to at least five feet above the ground.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/05/2018 10/05/2018	David Julian

LM Start	0.28	Rating **	A/W	Issue No.	18
LM End	0.28	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.346249 °	38.346331 °
				-121.540542 °	-121.540664 °
DWR ID	DWR_RD0755_01_f_2017_18				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:The damage consists of erosion of the lower waterside levee slope and bank approximately 27 feet in length along the east (left) bank of the Sacramento River. See attached pages for photos. Site location T06N R04E Section 28.					
Site ID No:327					
Site Designation:LMA-154					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:7/13/2017					
Notes: Pretty minor damage visible from the slope, site was originally identified by boat. Will look at again from waterside if there is time.					
Crown is a paved road. Original GPS was a little off, added correct point in start					

LM Start	0.28	Rating **	A/W	Issue No.	18 (cont)
LM End	0.28	Issue Type +	Ma	Location *	WS

Photo 1 of 3 : FA_2018_RD0755_177_18_20180925_00003.jpg



Photo 2 of 3 : FA_2018_RD0755_177_18_20180925_00004.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/05/2018 10/05/2018	David Julian

LM Start	0.28	Rating **	A/W	Issue No.	18 (cont)
LM End	0.28	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.346249°	38.346331°
				-121.540542°	-121.540664°
DWR ID	DWR_RD0755_01_f_2017_18				
Comment Code					
Inspector Comment					
<p>Levee Evaluation Comments</p> <p>Description: The damage consists of erosion of the lower waterside levee slope and bank approximately 27 feet in length along the east (left) bank of the Sacramento River. See attached pages for photos. Site location T06N R04E Section 28.</p> <p>Site ID No: 327</p> <p>Site Designation: LMA-154</p> <p>Repair Type: Erosion</p> <p>Rating: Area of Concern</p> <p>Field Date: 7/13/2017</p> <p>Notes: Pretty minor damage visible from the slope, site was originally identified by boat. Will look at again from waterside if there is time. Crown is a paved road. Original GPS was a little off, added correct point in start</p>					

Photo 3 of 3 : FA_2018_RD0755_177_18_20180925_00005.jpg



LM Start	0.43	Rating **	M	Issue No.	4
LM End	1.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.345593°	38.337197°
				-121.543263°	-121.564147°
DWR ID	DWR_RD0755_01_f_2014_4				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Evidence of active rodents on landside slope near the walnut trees. No bait stations observed.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/05/2018 10/05/2018	David Julian

LM Start	0.50	Rating **	M	Issue No.	17
LM End	0.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.345652°	38.345618°	
			-121.544482°	-121.545122°	
DWR ID	DWR_RD0755_01_f_2018_17				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	0.69	Rating **	M	Issue No.	26
LM End	0.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		38.345103°	38.345103°	
			-121.547918°	-121.547918°	
DWR ID	DWR_RD0755_01_f_2018_26				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/05/2018 10/05/2018	David Julian

LM Start	0.70	Rating **	A/W	Issue No.	33	
LM End	0.70	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.345057 °	38.345057 °	
				-121.548050 °	-121.548050 °	
DWR ID	18852					
Comment Code						
Inspector Comment						
FS_ID:17145 DS_ID:18852 EP_NO: 11222 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: It was working during field survey. A pump found 150 ft from the levee. Not sure whether the pump belong to this drainage system. FIELD_STRUCT_DESC: *ABANDONED* 16-inch steel drainage pipe sleeved through a 24-inch steel drainage pipe through the levee, invert elevation 8 feet below the crown. (Retention of a 12-inch drainage pipe sleeved through a 24-inch pipe through the levee, 8 feet below the crown, authorized under Automatic Board Order (ABO) issued as Permit No. 11222, 1975 - Green McKeown, Inc). [Additional Reference(s): DWR Levee Log, 2005, 12-inch inner pipe referenced. USACE Sacramento O&M Manual 111, May 1959, (RM 35.89)]. FS Date: 8/6/2013						

LM Start	0.70	Rating **	A/W	Issue No.	33 (cont)
LM End	0.70	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_17145_29292.jpg



WS view: pipe and siphon breaker on levee slope

Photo 2 of 3 : UCIP_FA_2018_17145_29293.jpg



WS view: 16-inch pipe sleeved through 24-inch pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/05/2018 10/05/2018	David Julian

LM Start	0.70	Rating **	A/W	Issue No.	33 (cont)	
LM End	0.70	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			38.345057 °	38.345057 °	
				-121.548050 °	-121.548050 °	
DWR ID	18852					
Comment Code						
Inspector Comment						
FS_ID:17145 DS_ID:18852 EP_NO: 11222 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: It was working during field survey. A pump found 150 ft from the levee. Not sure whether the pump belong to this drainage system. FIELD_STRUCT_DESC: *ABANDONED* 16-inch steel drainage pipe sleeved through a 24-inch steel drainage pipe through the levee, invert elevation 8 feet below the crown. (Retention of a 12-inch drainage pipe sleeved through a 24-inch pipe through the levee, 8 feet below the crown, authorized under Automatic Board Order (ABO) issued as Permit No. 11222, 1975 - Green McKeown, Inc). [Additional Reference(s): DWR Levee Log, 2005, 12-inch inner pipe referenced. USACE Sacramento O&M Manual 111, May 1959, (RM 35.89)]. FS Date: 8/6/2013						

Photo 3 of 3 : UCIP_FA_2018_17145_29295.jpg



WS view: 16-inch drainage pipe on levee slope.

LM Start	0.99	Rating **	M	Issue No.	29
LM End	0.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343835 °	38.343835 °
				-121.553162 °	-121.553162 °
DWR ID	DWR_RD0755_01_f_2018_29				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/05/2018 10/05/2018	David Julian

LM Start	1.10	Rating **	M	Issue No.	30
LM End	1.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.343373°	38.343373°
				-121.555188°	-121.555188°
DWR ID	DWR_RD0755_01_f_2018_30				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	1.12	Rating **	M	Issue No.	28
LM End	1.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.343300 °	38.341237 °
				-121.555507 °	-121.560113 °
DWR ID	DWR_RD0755_01_s_2017_28				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Remove vegetation from land side slope.					

Photo 1 of 1 : FA_2018_RD0755_177_28_20181009_00042.jpg



View looking upstream at vegetation on the land side slope (October 2018).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/05/2018 10/05/2018	David Julian

LM Start	1.23	Rating **	A/W	Issue No.	22
LM End	1.29	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.342992 °	38.342633 °
				-121.557572 °	-121.558622 °
DWR ID	DWR_RD0755_01_f_2017_22				

Comment Code

Inspector Comment

Levee Evaluation Comments

Description: The damage consists of erosion of the lower waterside levee slope and bank approximately 322 feet in length along the east (left) bank of the Sacramento River. See attached pages for photos. Site location T06N R04E Section 29.

Site ID No: 328

Site Designation: LMA-155

Repair Type: Erosion

Rating: Area of Concern

Field Date: 7/13/2017

Notes: Could not access most of the lower portion of the slope because of vegetation, but there was rip rap just downstream of the site. Looked like it may have been missing on part of the site. Erosion looked like it may be 1/2 the length reported. Crown is a paved road

LM Start	1.23	Rating **	A/W	Issue No.	22 (cont)
LM End	1.29	Issue Type +	Ma	Location *	WS

Photo 1 of 3 : FA_2018_RD0755_177_22_20180925_00008.jpg



Photo 2 of 3 : FA_2018_RD0755_177_22_20180925_00009.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0755 Randall

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.83	10/05/2018 10/05/2018	David Julian

LM Start	1.23	Rating **	A/W	Issue No.	22 (cont)
LM End	1.29	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.342992 °	38.342633 °
				-121.557572 °	-121.558622 °
DWR ID	DWR_RD0755_01_f _ 2017_22				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:The damage consists of erosion of the lower waterside levee slope and bank approximately 322 feet in length along the east (left) bank of the Sacramento River. See attached pages for photos.					
Site location T06N R04E Section 29.					
Site ID No:328					
Site Designation:LMA-155					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:7/13/2017					
Notes: Could not access most of the lower portion of the slope because of vegetation, but there was rip rap just downstream of the site. Looked like it may have been missing on part of the site. Erosion looked like it may be 1/2 the length reported. Crown is a paved road					

Photo 3 of 3 : FA_2018_RD0755_177_22_20180925_00010.jpg



LM Start	1.24	Rating **	C	Issue No.	10
LM End	1.32	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			38.343071 °	38.342426 °
				-121.557706 °	-121.559163 °
DWR ID	DWR_RD0755_01_f _ 2018_10				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 35.4 L					
Status: Repaired					
2017 Field Notes: Repaired by locals.					
Site History: 2003 - Toe and lower slope eroding, rock in water and a few pieces on the slope; rock at upstream and downstream ends.					
2005 - Looks a little worse. Two major holes with vertical banks and smaller intermittent pockets in between. Stone is present upstream, downstream, and at toe. 2008 - Repaired at both ends (50 ft of new stone) but middle remains unrepaired. 2011 - Site extended downstream to include new scour. 2013 - At the downstream end, behind tree, there is a new animal burrow. Tree has exposed roots.					
2015 - New rock placed at toe in middle of the site, but a hole remains behind the tree. 2016 - Repaired by locals.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Reclamation District No. 0755 Randall

Photo 1 of 1 : FA_2018_RD0755_177_13_20180925_00002.jpg



Vegetation on landside should be maintained to allow inspection and access to slope and toe.

Photo 1 of 3 : FA_2018_RD0755_177_24_20180925_00011.jpg

A photograph showing a shoreline. The water is a deep green color. The bank is composed of grey rocks and some dry, light-colored vegetation. In the foreground, there is a dense patch of green and yellow grasses or reeds. A shadow of the person taking the photo is cast onto the vegetation in the lower-left corner.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

Reclamation District No. 0755 Randall

A wide-angle photograph of a large body of water, possibly a reservoir or lake. The foreground is dominated by dry, yellowish-brown grass and some small green plants. The water is a deep blue-green color with gentle ripples. In the background, a line of green trees and bushes borders the water, with a few buildings visible on a slight rise in the distance under a clear blue sky.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable	A : Acceptable N : Not Inspected/Rated	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable C : Corrected	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable A/W : Acceptable but Monitor & Maintain	En : Enforcement